Docket No.: BELL-0136/01180 Appln. No: Not yet and the cet LRN Under Number Pooling Inventor(s): Roderick Holland

Attorney: Susan C. Murphy Phone No.: 215-568-3100 Sheet 1 of 5




FIGURE 1
PRIOR ART

Docket No.: BELL-0136/01180 Appln. No: Not yet Assigned
Tigogram and Method for Identifying Contaminated Telegram: Numbers

an rect LRN Under Number Pooling Inventor(s): Roderick Holland

Attorney: Susan C. Murphy Phone No.: 215-568-3100 Sheet 2 of 5





FIGURE 2 PRIOR ART

Docket No.: BELL-0136/01180 Appln. No: Not yet Assigned Title: Symmand Method for Identifying Contaminated Telephon and Correct RN Under Number Pooling

Inventor(s): Roderick Holland

Attorney: Susan C. Murphy Phone No.: 215-568-3100 Sheet 3 of 5



낦

Docket No.: BELL-0136/01180 Appln. No: Not system and Method for Identifying Contaminated Telephone Numbers orrect LRN Under Number Pooling

Inventor(s): Roderick Holland

Attorney: Susan C. Murphy Phone No.: 215-568-3100 Sheet 4 of 5




FIGURE 4

Docket No.: BELL-0136/01180 Appln. No: Not yet Assigned
Title: System and Method for Identifying Contaminated Telephone
and Correct RN Under Number Pooling
Inventor(s): Roderick Holland
Attorney: Susan C. Murphy Phone No.: 215-568-3100 Sheet 5 of 5

SERVICE PROVIDER REQUESTS BLOCK 302 POOLING ADMINSTRATION APPROVES REQUEST 304 **BLOCK RELEASED TO** SERVICE PROVIDER 306 NPAC RELEASES BLOCK TO **SERVICE PROVIDER** 308 **NPAC BROADCASTS MESSAGE TO ALL SERVICE PROVIDERS** 310 NPAC DATABASE ACCESSED FOR LIST OF CONTAMINATED **NUMBERS** 512 NPAC DATABASE ACCESSED FOR "NEW" LRN 514 BS AND FMS RECEIVE DATA/ **UPDATE FILES** 516

FIGURE 5